## Technical Bulletin

Bulletin No: PRO-01-23 Effective Date: 10/30/82 Cancels: NA Page: 1 of 1

## Subject: FORD OFFSET MOUNT AND CATERPILLAR 3406 COMPRESSORS

Traditionally Bendix remanufactured compressors have been supplied with the necessary mounting gaskets, o-rings, etc. Two exceptions to this general practice currently exist and are noted below.

We are currently working to correct this situation and will include these components with the basic compressors in the near future. In the interim these parts must be obtained separately from the appropriate O.E. parts outlet. Please record the O.E. part numbers on the catalog pages shown.

1. The base gasket for Ford offset mount compressors is not supplied. The Ford part number for this gasket is D4TZ-2B885-A. The remanufactured basic compressors affected are:

| PC. NO. | COMPRESSOR MODEL | <u>CATALOG PAGE</u> |
|---------|------------------|---------------------|
| 286558  | TuFlo 501        | 01-E-12             |
| 286561  | TuFlo 501        | 01-E-12             |
| 286562  | TuFlo 501        | 01-E-12             |

2. The crankshaft o-ring on flange mounted compressors for the Cat. 3406 engine is not supplied. The Cat. part number for this o-ring is 5H2767. The remanufactured basic compressors affected are:

| PC. NO. | COMPRESSOR MODEL | <u>CATALOG PAGE</u> |
|---------|------------------|---------------------|
| 285131  | TuFlo 500        | 01-D-33             |
| 286546  | TuFlo 501        | 01-E-13             |
| 288710  | TuFlo 600        | 01-F-17             |
| 289349  | TuFlo 700        | 01-K-11             |

